

CHANGES AND ADDITIONS  
BULLETIN NO. 50 (ISSUE 2) AND BULLETIN NO. 53 (ISSUE 1)  
PARTS - KEYBOARD TAPE PERFORATOR (TELETYPESETTER)

BULLETIN NO. 50, PAGE 9  
BULLETIN NO. 53, PAGE 15

THE 85356 PUNCH BLOCK ASSEMBLY HAS BEEN REDESIGNED AND ASSIGNED A NEW ASSEMBLY NUMBER (112645). THE OLD STYLE PUNCH BLOCK ASSEMBLY IS NO LONGER FURNISHED. ON ORDERS FOR OLD STYLE BLOCKS, NEW STYLE BLOCKS WHICH ARE FULLY INTERCHANGEABLE WITH THE OLD STYLE WILL BE FURNISHED.

THE SKETCHES BELOW ILLUSTRATE THE DIFFERENCE BETWEEN THE OLD AND NEW STYLE PUNCH BLOCKS, AND IT SHOULD BE NOTED THAT THE 75121 SHEDDER AND 75120 WEARING STRIP ARE REPLACED BY A 110904 RETRACTOR PLATE, AND THE 122-80 SHEDDER GUIDES ARE NOT USED. THE 75121 SHEDDER AND 75120 WEARING STRIP ARE NO LONGER BEING FURNISHED. WHEN IT IS DESIRED TO REPLACE A 75121 SHEDDER AND/OR 75120 WEARING STRIP, A 110904 RETRACTOR PLATE SHOULD BE ORDERED INSTEAD.

